MSB315-75 MSB817-53 MSB869-26 Page 1 of 4 2 July 2007



SERVICE BULLETIN NO. MSB 315-75 SERVICE BULLETIN NO. MSB 817-53 SERVICE BULLETIN NO. MSB 869-26

I. TECHNICAL DETAILS

1.1 Category:

Mandatory

1.2 Airplanes affected:

TCDS: 315 FAA TCDS: G39EU

 Model
 Serial Number

 G103 TWIN II
 3501-3729

 G103 TWIN II
 3730-3878

 G103A TWIN II ACRO
 3544-34078 (K)

 G103C TWIN III ACRO
 34101-34203

 G103C TWIN III
 36001-36014

TCDS: 817 FAA TCDS: G43EU

Model Serial Number

G 109 all G 109B all

TCDS: 869 FAA TCDS: G57EU

Model Serial Number G 103C TWIN III SL 35001-35051

1.3 Time of Compliance:

before the next flight

1.4 Subject:

ATA-Code: 27-10, 27-30

Aileron Control, Elevator Control

G 103 G 109 MSB315-75 MSB817-53 MSB869-26 Page 2 of 4 2 July 2007



1.5 Reason:

GROB received a report that a rear control stick (welded design) failed on a G 103 TWIN II after about 2600 flight hours.

Although no extensive investigation (metallurgical investigation) could not be performed up to now, a one-time inspection of the rear control stick respectively the RH stick on G 109/ G 109B (same design standard than on the concerned type) is mandatory as a precautionary action to find possible, unnoticed damages and/ or corrosion.



1.6 Concurrent documents:

Maintenance Manual of the affected models

1.7 Approval Note:

The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.030.

MSB315-75 MSB817-53 MSB869-26 Page 3 of 4 2 July 2007



1.8 Accomplishment/ Instructions

- 1.8.1 Remove control stick cover and release attachment bolt and remove upper control stick.
- 1.8.2 Inspect upper and lower part of the control stick for damage and corrosion.

If no damage is found proceed with para. 1.8.6.

If any damage is determined proceed as follows:

- 1.8.3 De-rig aircraft and remove control stick unit as far as required.
- 1.8.4 Determined damages or corrosion must be removed in the approved range I.A.W. "Aircraft Inspection and Repair FAA AC 43.I3-IA" or new parts must be installed.

Note: The national regulations must be followed when applying the FAA AC 43.I3-IA!

- 1.8.5 Re-install control stick unit. If necessary use new attachment parts.
- 1.8.6 Install control stick. Apply and tighten attachment bolt. The standard torque is to be used.
- 1.8.7 Check controls for free and easy movement for correct sense of deflection.

1.9 Repetitive Actions

The inspection must be repeated during each annual inspection/ 100 hours inspection.

1.10 Mass (Weight) and CG:

N/A

MSB315-75 MSB817-53 MSB869-26 Page 4 of 4 2 July 2007



II. PLANNING INFORMATION

2.1 Material & Availability:

Necessary parts may be ordered from the manufacturer. Aircraft S/N must be advised.

2.2 Special Tools:

N/A

2.3 Labour costs:

Approx. 1 hour for inspection

2.4 Reference documents:

N/A

2.5 Credit:

N/A

III. REMARKS

- **3.1** The correct execution of the instructions must be performed by an authorized aviation workshop or a licensed inspector and has to be certified in the logbook by an authorised inspector.
- **3.2** If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- **3.3** For questions and assistance please contact:

Rudi Vodermeier,

phone: +49 8268 998139

Michael Reinhold

phone: +49 8268 998105 fax: +49 8268 998200

e-mail: productsupport@grob-aerospace.de

G 103 G 109