

Subject: Canopy fasteners

Effectivity: Sailplane CLUB ASTIR II and
STANDARD ASTIR II, serial-number 5001
up to 5061.

Accomplishment: Not later than 15.08.1980

Reason: Avoidance of self-acting opening of the
canopy during the flight.

Instruction: Change of the springs on the fasteners
according to repair instruction of
TM 306-14.

Material: Material according to repair instruction
of TM 306-14 to be obtained from the
manufacturer.

**Weight and
Balance:** No change

Remarks: The procedure can be carried out by
an experienced person and must be signed
in the logbook by a qualified inspector
or by a recognized aircraft manufacturer.

Mindelheim-Mattsies, 09.06.1980
West Germany

signed by order Dipl. Ing. H. Wilser



Certified by LBA
(Luftfahrt-Bundesamt)
16.06.1980