



ALERT SERVICE BULLETIN NO. ASB306-36

I. TECHNICAL DETAILS

1.1 Category:

ALERT

1.2 Airplanes affected:

G 102 Standard Astir III	all S/N
G 102 Club Astir III	all S/N
G 102 Club Astir IIIb	all S/N

1.3 Time of Compliance:

Prior to next flight

1.4 Subject:

ATA-Code: ---

Elevator - Flutter

1.5 Reason:

During the operation of a GROB G 102 Club Astir IIIb, flutter of the elevator occurred. This could result in damages to the elevator and therefore reduction of the controllability. Since the same design is used at the G 102 Standard Astir III and the G 102 Club Astir III those models are also affected.

1.6 Concurrent documents:

None

1.7 Approval Note:

The technical information contained in this document has been approved under the authority of JAA Design Organization Approval No. LBA.NJA.008.

1.8 Accomplishment/ Instructions

G 102 Standard Astir III
G 102 Club Astir III / IIIb



Due to possible elevator flutter, further operation of the airplanes is prohibited until otherwise noticed by GROB (refer to remarks, item 3.1).

1.9 Repetitive Actions

None

1.10 Mass (Weight) and CG:

N/A

II. PLANNING INFORMATION

2.1 Material & Availability:

N/A

2.2 Special Tools:

N/A

2.3 Labour costs:

N/A

2.4 Reference documents:

N/A

2.6 Credit:

N/A

III. REMARKS

- 3.1 GROB has started an investigation of the incident. As soon as the results are available corrective actions will be worked out and made available to the operator by means of a

G 102 Standard Astir III
G 102 Club Astir III / IIIb



Service Bulletin.

- 3.2** If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3** For questions and assistance please contact:
Rudi Vodermeier , Head of Product Support,
phone: +49 8268 998139
fax: +49 8268 998200
e-mail: productsupport@grob-aerospace.de

G 102 Standard Astir III
G 102 Club Astir III / IIIb