

Subject: Revision of the Maintenance Manual/ Change of Inspection and Maintenance Periods

Concerned: G 103C TWIN III SL, alle S/N's

Urgency: not later than 31 December 1993

Procedure: Practice and new experiences, gained during maintenance and repair, require changes in the inspection and maintenance periods.

Action: Revision 5 (5/ 27.07.93) must be included into the Maintenance Manual. The pages, listed on page 0.1A, must be exchanged.

Material: The pages of the Maintenance Manual are supplied with the Service Bulletin.

Weight and Balance: not concerned

Remarks:


1. The revision can be performed by a competent person or an authorized aviation workshop and has to be certified in the logbook by an authorized inspector.
2. If you have sold your motorglider in the meantime, would you kindly pass this information on to the new owner and forward his name and address and aircraft S/N to us.

Mattsies, 27 July 1993

LBA approved:

This Service Bulletin is originally written in German and approved by the German LBA on ~~14~~ October 1993 and is signed by Mr. U. Kopp.

The translation has been accomplished to the best of our knowledge and judgement. In case of doubt, the German original is authoritative.



Dipl.Ing. J. Altmann
(Airworthiness engineer
certification staff)