

Service Bulletin TM 306-21

CLUB ASTIR II STANDARD ASTIR II

Subject

Exchange of canopy hinge.

Effectivity:

Glider CLUB ASTIR II all serial numbers and glider STANDARD ASTIR II

all serial numbers.

Accomplishment :

Latest by April 30, 1983

Reason:

The mentioned gliders had sometimes a failure of the canopy hinge which requires the exchange of the hinge

at all serial numbers.

Instructions :

Exchange of the canopy hinge no. 104-2601 made of aluminum casting

against the canopy hinge no. 102C-2620 made of aluminum sheet according to repair instructions to TM 306-21 dated 20.01.1983.

Material:

Material and repair instructions for TM 306-21 are available at the manu-

facturer.

Weight and balance :

No influence.

Remarks:

The procedure can be carried out by an experienced person and must be signed in the logbook by a qualified inspector or by a recognized aircraft

manufacturer.

Mattsies, 20.01.1983

LBA approved on : 4. Feb. 1983

signed i.A. Dipl.-Ing. H. Wilser HonA Wilser