

This Service Bulletin substitutes the Service Bulletin TM 869-1 dated 19 February 1992.

Subject: Revision of the flight and maintenance manual

Concerned: G 103 C TWIN III SL, S/N 35001 - 35039
(as of S/N 35040 standard)

Urgency: before 30 June 1992

Procedure: A revision of the flight and maintenance manual is required for the inclusion of corrections and additional information.

Actions: The following pages must be replaced:
(Date of revision: 1/ 19.02.92)

- Flight Manual/ Flughandbuch (German Issue):
pages 0.1, 0.2, 0.3, 0.4, 0.5, 2.5, 4.13,
7.3, 7.7, 7.12
- Maintenance Manual/ Wartungshandbuch (German Issue):
pages 0.1, 0.2, 0.3, 0.4, 1.3, 2.6, 2.7, 6.10,
6.13, 8.2, 9.7, 9.9, 10.1, 11.3

Weight and Balance: not concerned


Remarks:

1. The revision must be carried out at an authorized aviation work shop and certified in the log book by an authorized inspector.
2. If you have sold your motorglider in the meantime, would you kindly pass this information on to the new owner and forward his name and address and aircraft s/n to us.

Mattsies, 10 April 1992

LBA approved

This Service Bulletin was originally written in German and approved by the German LBA on the 26 June 1992 and is signed by Mr. U. Kopp. The translation has been accomplished to best of our knowledge and judgement. In case of doubt, the German original is authoritative.



Dipl. Ing. J. Altmann
(Airworthiness engineer
certification staff)