

Subject: Deviation of record of measurements (Einstellbericht).

Effectivity: Sailplane ASTIR CS from serial-no. 1001 to 1437.

Accomplishment: Record of measurement (Einstellbericht) should be corrected on or before the next periodical inspection.

Reason: Uncorrect figure for the range of wing sweep back.

Instructions: The aircraft owner should place this letter TM 102-5 with the aircraft paper entitled "Einstellbericht". Note: Disregard that figure 0 ± 20 found in the column entitled "Soll" and following the heading of "Tragflügelpfeilung". Insert for such deleted figure the following:
 $0 + 20$
 $0 - 40$

Material: None.

Weight and ballance: No change.

Remarks: None.

Mindelheim-Mattsies, den 8. 2. 1977

GROB-FLUGZEUGBAU

gez. i. A. Dipl. Ing. H. Wilser

H. Wilser

LBA-certified at
5. April 1977

