

## Service Bulletin TM 869-12

GROB G 103 C TWIN III SL

Subject:

Installation of the VHF-COM-antenna BECKER type 1A005

Concerned:

G 103 C TWIN III SL, all S/N's

**Urgency:** 

Optional

Procedure:

Within a supplementary type certification, installation of the VHF-COM-antenna Becker type 1A005 in the canopy frame of the fuselage, which improves radio communication, has been approved.

Actions:

The removal of the existing VHF-COM-antenna (from the nose of the fuselage) and the installation of the VHF-COM-antenna BECKER type 1A005 must be performed in accordance with Installation Instructions No. 869-12 to Service Bulletin TM 869-12.

Material:

The material is listed in the Installation Instructions No. 869-12.

Weight and Balance:

negligible

Remarks:

- 1. The exchange of the VHF-COM-antenna will be only performed by GROB up to now and has to be certified in the logbook by an authorized inspector.
- 2. If you have sold your motorglider in the meantime, would you kindly pass this information on to the new owner and forward his name and address and aircraft S/N to us.

Mattsies, 23 December 1992

## LBA approved:

This Service Bulletin is originally written in German and approved by the German LBA on the  $\upmu$  January 1993,

The translation has been accomplished to the best of our knowledge and judgement. In the case of doubt, the German original is authoritative.

Dipl.ing. J. Altmann (Airworthiness engineer certification staff)