



This Technical Information replace the TM 306-20 dated April 6, 1982

Subject: Difference from the German data sheet no. 306 for sailplanes with certification in Italy.

Effectivity: Sailplanes GROB G 102 "CLUB ASTIR III", "CLUB ASTIR IIIb" and "STANDARD ASTIR III" from no. 5501.

Accomplishment: Modifications for the purpose of certification in Italy.

Reason: The certification in Italy requires the following modifications.

- Instructions:
1. Modification of the Flight Manual GROB G 102 "CLUB ASTIR III", "CLUB ASTIR IIIb" and "STANDARD ASTIR III".
Edition for Italy published January 1981 with changes on pages 7 and 18 dated April 6, 1982 and change on page 1, 1b and 14 dated Sept. 7, 1982.
 2. Modification of the Maintenance Manual GROB G 102 "CLUB ASTIR III", "CLUB ASTIR IIIb" and "STANDARD ASTIR III".
Edition for Italy published January 1981 with changes on pages 1, 1b and 19 dated April 6, 1982.

Remarks: The correct action has to be certified by an authorized inspector of the manufacturer.

Mindelheim-Mattsies, September 7, 1982

i. A.

Horst Wilser

Dipl. Ing. Horst Wilser

LBA acknowledged



[Signature]
28. Sep. 1982

Datum	ersetzt Ausgabe vom	Bearbeitung		Seite
-------	---------------------	-------------	--	-------