



Subject: Difference from the German data sheet no. 315 for sailplanes with certification in Italy.

Effectivity: Sailplanes GROB G 103 "TWIN II", from serial no. 3501.

Accomplishment: Modifications for the purpose of certification in Italy.

Reason: The certification in Italy requires the following modifications.

Instructions:

1. Modification of the Flight Manual GROB G 103 "TWIN II".
Edition for Italy published December 1980 with changes on pages 1, 1a, 7, 8, 10, 14, 19, 21a and 25 dated July 7, 1982.
2. Modification of the Maintenance Manual GROB G 103 "TWIN II".
Edition for Italy published December 1980 with modifications dated November 19, 1981 and with changes on pages 2, 2a, 14, 22, 25 and 26 dated July 7, 1982.

Remarks: The correct action has to be certified by an authorized inspector of the manufacturer.

Mindelheim-Mattsies, September 6, 1982

i. A.

Horst Wilser

Dipl. Ing. Horst Wilser

LBA acknowledged



R. ...
23. Sep. 1982

Datum

ersetzt Ausgabe
vom

Bearbeitung

Seite